304 East Lombard Street (Commercial Building)
Baltimore (Independent City)
Maryland

HABS No. MD-919

HABS MD, 4-BALT, 155-

PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

HISTORIC AMERICAN BUILDINGS SURVEY
MID-ATLANTIC REGION NATIONAL PARK SERVICE
DEPARTMENT OF THE INTERIOR
PHILADELPHIA, PENNSYLVANIA 19106


Form 10~920 (June 1983)

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

HABS MD. 4-BALT, 155-

ARCHITECTURAL DATA FORM

STATE	COUNTY		TOWN OR VICINITY	
Maryland			Baltimore (Independent City)	
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME)			 	HABS NO.
304 East Lombard Street (Commercial Building)			MD-919	
SECONDARY OR COMMON NAMES OF STRUCTURE				
COMPLETE ADORESS (DESCRIBE LOCATION FOR RURAL SITES) 304 East Lombard Street				
OATE OF CONSTRUCTION (INCLUDE SOURCE)		ARCHITECT(S) (INCLUDE SOURCE)		
Circa 1905		Builder: Frank Fox		
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE) The commercial building at 304 East Lombard Street was part of the rebuilding of the commercial center of Baltimore following the 1904 fire which destroyed 140 acres of property. The area includes some of the finest early twentieth century architecture in STYLE (IF APPROPRIATE)				
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS)				
Brick bearing walls with wood floor joists, flat roof and wood rafters.				
APE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE)				
Four story with basement. See sketch plan.				
EXTERIOR FEATURES OF NOTE Large, four-story, brick arch with carved ketstone on front elevation. Window size and shape within the arch have been altered by recent modifications. An alley on the west side of the building allowed windows on that side. These are wood double-hung with metal covered shutters. Rear and east walls show no evidence of windows.				
INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED)				
Original plan appears to be a large open room on each floor with the stairs along the east wall and a dumbwaiter in the northeast corner. This would indicate a loft type commercial layout. Recent interior walls were added to create office space on the				
upper floors and a restaurant on the first floor. MAJOR ALTERATIONS AND ACCITIONS WITH DATES				
Cornice removed, aluminum curtain wall with windows and doors placed in the front arch.				
PRESENT CONDITION AND USE				
Good condition				
OTHERINFORMATION AS APPROPRIATE Structure to be demolished to make way for new Baltimore Federal Savings and Loan building.				
SOURCES OF INFORMATION (INCLUOING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.) Preliminary Doucment Study: Block 1370 by Timothy W. Jones and Kenneth J. Basalik of Cultural Heritage Research Services, Inc.				
COMPILER, AFFILIATION Edward T. Hinderliter, R.A.	, Cultural Her	itage Research Se	ervices,	DATE November 1982



NOT TO SCALE

TYPICAL FLOOR LAYOUT

304 E. LOMBARD STREET.